
















TYPE: Hilux Revo
MODEL: KUN/GGN/GUN 125, KUN/GUN 126, GUN13
YEAR: 2015 on
DETAIL: 4x4



FRONT			REAR		
QTY	PART NUMBER	PRICE	QTY	PART NUMBER	PRICE
COIL SPRING			LEAF SPRING		
Single Cab					
	Linear Rate Standard Height (15mm Lift) 50 - 100Kg Accessories	1 C59-718	B		
	Linear Rate Raised Height (45mm Lift) Up to 60Kg Accessories	1 C59-296	B		4+3 Leaves Raised Height (45mm Lift) Medium Duty Up to 100Kg Constant Load 2 L59-174-R
	Linear Rate Raised Height (45mm Lift) 80-100Kg Accessories	1 C59-300	B		5+3 Leaves Raised Height (45mm Lift) Heavy Duty 250-300Kg Constant Load 2 L59-175-R
Dual Cab					
	Linear Rate Standard Height 50 - 100Kg Accessories	1 C59-718	B		6+3 Leaves Raised Height (45mm Lift) Super Heavy Duty 580Kg Constant Load 2 L59-176-R
	Linear Rate Raised Height (45mm Lift) Comfort Option Up to 40Kg Accessories	1 C59-302	B		2+1 Leaves Parabolic Raised Height (50mm Lift) Comfort Option Up to 60Kg Constant 2 L59-178-RP
	Linear Rate Raised Height (45mm Lift) Heavy Duty Up to 40Kg Accessories	1 C59-350	B	SHACKLE BUSH KIT	
	Linear Rate Raised Height (45mm Lift) Heavy Duty Up to 40-80Kg Accessories	1 C59-354	B		Kit Contains: 2 x PB59-1503 4 x PB59-1501 4 x PB59-1502 1 PB59-1094K
	Linear Rate Raised Height (45mm Lift) Heavy Duty 80-120Kg Accessories	1 C59-736	B	U-BOLT KIT	
SHOCK ABSORBER					
	Heavy Duty Twin Tube Gas	2 GS59-228			Kit Contains: 2 x UB59-437 2 UB59-437K
	Monotube Remote Reservoir Adjustable Spring Seat Heavy Duty Original Setting of X = 226mm/8.89"X - Centre of Eye to Spring Seat	2 MR59-50228		SHOCK ABSORBER	
					Heavy Duty Twin Tube Gas 2 GS59-229
					Heavy Duty Monotube Remote Reservoir 2 MR59-50229
STRUT CAP			SHACKLE		
	Strut Top Caps	2 SC59-001			Rear of Rear Spring 2 SK59-064
				PIN	
					Front of Rear Spring Greasable: Fit in Pairs 2 SP59-060
				This part is recommended with all kits as the fuel tank location inhibits original bolt removal.	