

THE SUPERIOR ALTERNATIVE - SHOCK ABSORBERS -

FRONT		September, 2004		REAR
Steering Damper	Shock Absorber	YEAR	MAKE & MODEL	Shock Absorber

DAIHATSU				
SD15-031	GS59-635	78 – 84	F10, F20, F50, F60	GS59-635
SD15-031	GS59-635	11/79 – 03/84	Scat F25, F55, F65	GS59-631A
SD15-031	GS15-639S	84 – 08/93	Rocky F70, F75, F80, F85	GS15-639S
SD15-031	GS15-639A	84 on	Rocky Pickup F77, F87	GS59-631A
	GS43-082S	10/98 on	Feroza CX12, F300	GS15-639S
	GS15-463W	93 on	Rocky F78, F98	

FORD				
	GS43-082S	85 – 02/99	Courier PC, PD 2WD Ute	GS59-636
	GS19-082P	87 on	Courier UFS 4WD	GS19-081T
	GS43-082S	02/99 on	Courier PE 2WD Ute	GS59-636
	GS43-082	79 – 81	Econovan (Dual Rear Wheels)	GS59-635
	GS43-082	81 – 12/83	Econovan 1300, 1600, 2200 (Chassis SGMA B W-015027 on) Van	GS59-636
	GS43-082	81 – 12/83	Econovan 1300, 1600, 2200 (up to Chassis SGMA B W-015026) Van	GS59-635
		84 – 90	Econovan 1800, 2000, 2200 Dual Rear Wheels	GS59-635
		84 – 90	Econovan 1400, 1800, 2000, 2200 Single Rear Wheel and 1400 Dual Rear Wheel	GS59-636
		90 – 10/97	Econovan Cab Chassis, Tray Top Dual Rear Wheels, Ute	GS59-635
		90 – 10/97	Econovan 4WD Van	GS59-636
		90 – 10/97	Econovan Single Rear Wheels Van	GS59-636
	GS19-082P	03 on	Everest 2WD & 4WD	GS19-081T
SD45-034	GS45-114	88 – 09/89	Maverick Y60 SWB LWB	GS45-115
SD45-034	GS45-114	88 – 09/89	Maverick Y60 Pickup	GS45-115
SD45-036	GS45-114	09/89 on	Maverick Y60 SWB LWB	GS45-115
SD45-036	GS45-114	09/89 on	Maverick Y60 Pickup	GS45-115
	GS19-082P	90 – 97	Raider JC, UV 4WD	GS19-081T
		84 – 10/97	Spectron Single Rear Wheel Van	GS59-636
	TS90-211	81 – 89	Trader 0811, 0509, 0812 WF Round Head Light	GS59-635
	TS90-211	89 on	Trader 0811, 0812 WG Square Head Light	GS59-635

HOLDEN / ISUZU				
SD57-030	GS57-085	85 – 87	Drover QB	GS57-086
	GS45-087	82 – 10/86	Jackaroo Trooper UBS 13, 16, 52	GS59-636
	GS45-087	11/86 – 92	Jackaroo Trooper UBS 16, 17, 52, 55	GS21-637S
	GS21-463	92 – 04	Jackaroo UBS 69 2WD & 4WD Wagon	GS21-015B
	GS21-463	95 – 98	Frontera UT, MB All Models	GS21-016
	GS21-463	99 on	Frontera 5 Door V6 UES, MX All Models	GS43-781
	GS21-463	95 – 96	Montery UBS 4WD Wagon	GS21-015B
	GS45-087	77 – 88	Rodeo TFR, KB2#, KBD2# 2WD	GS59-636
	GS45-087	80 – 07/88	Rodeo TFR KB4# 2WD	GS59-636
	GS45-097	88 – 96	Rodeo TFR All 2WD	GS59-636
	GS45-097	96 – 03	Rodeo TFR R7, R9 (Excluding V6 Ute) 2WD	GS59-636
	GS43-082S	96 – 03	Rodeo TFR R7, R9 V6 All	GS59-636
	GS21-463	88 – 03	Rodeo TFS# 4WD	GS43-081B
	GS21-463	03 on	Rodeo TFS 77 4WD	GS59-636

	GS43-082	81 – 91	Shuttle WFR 4x2 Van	GS59-635
	GS21-463	to 95	MU USC 17, 55 Leaf Spring Rear	GS59-636
	GS21-463	89 on	Wizzard UC355, 69 UES 73 4WD	GS21-015B

HYUNDAI

	GS45-087	00 on 08/01 on	Santa FE Terracan	GS59-940 GS59-223
--	----------	-------------------	----------------------	----------------------

JEEP

SD29-040	GS29-424	94 on	Cherokee XJ	GS29-425
SD29-040	GS29-424	04/96 on	Grand Cherokee ZJ	GS29-683
SD29-040	GS29-721	10/96 on	Wrangler TJ	GS29-722
	GS29-723	10/01 on	Cherokee KJ	GS29-724

LADA

	GS33-087B	78 on	Niva 2121	GS33-635W
--	-----------	-------	-----------	-----------

LANDROVER

SD51-011	GS51-090	Pre 58	Series II, IIA, III LWB	GS51-015C
SD51-011	GS51-090	58 on	Series II, IIA, III LWB	GS51-117
SD51-011	GS51-090	58 on	Series II, IIA, III SWB	GS51-015C
SD51-011	GS51-116	71 – 95	Range Rover 3.5L, 3.9L V8 All Models	GS51-117
SD51-011	GS51-116	05/95 on	Range Rover ML3, 7 - 4.0L V8 Coil Suspension	GS51-117
SD51-011	GS59-683	05/95 – 00	Range Rover ML3, 7 - 4.0L V8 with Air Suspension	GS51-117
SD51-011	GS51-116	91 – 03/99	Discovery Series I, II	GS51-117
SD51-502	GS51-118	03/99 on	Discovery	GS51-119
SD51-032	GS51-116	84 on	Defender SWB 90 Series	GS51-117
SD51-032	GS51-116	84 – 96	Defender LWB 110 County	GS51-117
SD51-032	GS51-116	92 – 99	Defender LWB 110, 130 Series	GS51-117

MAZDA

	GS43-082	10/77 – 85	B1800, B2000, B2200 2WD	GS45-077
	GS43-082S	85 – 91	B2000, B2200, B2600 2WD	GS59-636
	GS43-082S	01/92 on	B2200, B2500, B2600 2WD Bravo	GS59-636
	GS19-082P	87 on	B2200, B2500, B2600 4WD Bravo	GS19-081T
	GS43-082	05/78 – 81	E2000 Van and Pickup	
	GS43-082	03/81 – 84	E1400, E1600, E2200 Dual Rear Wheel	GS59-635
	GS43-082	03/81 – 84	E1400, E1600, E2200 single Rear Wheel	GS59-636
		02/84 – 86	E1400 Single and Dual Rear Wheel	GS59-636
		02/84 – 93	E1600, E1800, E2000, E2200 Single Rear Wheel	GS59-636
		02/84 – 93	E1600, E1800, E2000, E2200 Dual Rear Wheel	GS59-635
		94 – 97	E1800, E2000, E2200	GS59-635
		03/97 on	E2000, E2500	GS59-636
		77 on	Parkway 26 Bus	GS45-114
	TS90-211	81 – 88	WE T2000, T3000, T3500-4100 Round Head Lights	GS59-635
	TS90-211	89 on	WG T3500 2WD Square Head Lights	GS59-635
		88 on	T3500 4WD	GS59-635
	TS90-211	89 on	T4000, T4100, T4600	GS59-635

MITSUBISHI

		98 – 07/00	Challenger K96 Leaf Rear	GS59-635
	GS43-082S	06/00 on	Challenger Coil Rear	GS43-785
	GS43-082	89 – 96	Delica 4WD P25W, P35W 2.4L Turbo	
	GS43-082	05/79 – 86	L200 MA, MB, MC, MD 2WD	GS59-636
SD45-022	GS43-082	05/79 – 86	L200 MA, MB, MC, MD 4WD	GS43-636

	GS43-082	04/80 – 10/86	L300 SA – SE 2WD	GS59-635
	GS43-082	05/83 – 10/86	L300 SC – SE 4WD	GS43-785
	GS43-082S	11/86 – 12/94	L300 SF – SH Express Starwagon Van 2WD	GS43-785
	GS43-082	11/86 – 94	L300 SF – SH Express Starwagon Van 4WD	
	GS43-082S	09/94 on	L300 SJ, WA Express Starwagon Van 2WD	GS59-635
SD43-017	GS43-082	82 – 06/91	Pajero NA – NG SWB & LWB Leaf Rear	GS59-636
	GS43-082	88 – 06/91	Pajero NF, NG V6 Coil Rear	GS43-785
	GS43-082S	07/91 – 00	Pajero NH1, 3, NJ1 LWB Leaf Rear	GS59-636
SD43-017	GS43-082S	06/91 – 00	Pajero NH5, 6, 7, NJ3, 5, 6, 8, NK, NL Coil Rear	GS43-781
		06/91 – 00	Pajero Coil Rear (Big Bore)	GS43-788
	GS43-783	00 on	Pajero NM, NP V7# Series (SWB & LWB)	GS43-784
	GS43-082	10/86 – 11/96	Triton ME – MH, MK, MJ 2WD	GS59-636
SD45-022	GS43-082	10/86 – 11/96	Triton ME – MH, MJ, L200 Pick-Up 4WD	GS43-081B
	GS43-082S	11/96 on	Triton MK or L200 4WD	GS43-081B

NISSAN

	GS45-097	65 – 79	520 – 521, N620, 1500 2WD	GS59-631A
	GS45-097	80 – 08/85	720 2WD	GS59-631A
	GS45-097	80 – 12/81	720 4WD	GS59-631A
	GS45-097	82 – 85	720 4WD	GS59-636
SD45-035	GS45-097	09/85 on	Navara D21, 4WD D22 King Cab	GS43-785
	GS45-087	86 – 02/97	Navara D21 2WD	GS59-635
	GS45-097	02/97 on	Navara D22 2WD	GS59-635
SD45-035	GS45-087	10/87 – 95	Pathfinder WD21	GS59-636
	GS45-077	61 – 79	Patrol G60	GS45-077
SD45-022	GS45-077	80 – 08/83	Patrol 160 MQ	GS45-076
SD45-022	GS45-077	08/83 – 88	Patrol 160 MK	GS45-076
	GS51-116	89 on	Patrol Y260	GS45-115A
SD45-034	GS45-639B	88 – 09/89	Patrol Y60 GQ Pickup Leaf Spring	GS45-081P
SD45-036	GS45-639B	08/89 on	Patrol Y60 GQ Pickup Leaf Spring	GS45-081P
SD45-034	GS45-114	88 – 08/89	Patrol Y60 GQ SWB LWB Coil	GS45-115
SD45-036	GS45-114	08/89 on	Patrol Y60 GQ SWB LWB Coil	GS45-115
SD45-036	GS45-114	92 - 99	Patrol Y60 GQ Pickup Coil	GS45-115
SD51-011	GS45-114	01/99 on	Patrol Y61 GU Pickup Lear Rear	GS45-081P
SD51-011	GS45-114	05/99 on	Patrol Y61 GU Pickup Coil Rear	GS45-115
SD51-011	GS45-114	97- 02/00	Patrol Y61 GU SWB LWB	GS45-115
SD45-501	GS45-114	02/00-09/01	Patrol Y61 GU SWB LWB	GS45-115
	GS21-463	03/97 on	Terrano R20	GS59-636
	GS57-085	73 – 03/78	Urvan E20	GS59-631A
	GS45-097	78 – 80	Urvan E20	GS59-631A
	GS45-097	11/80 – 86	Urvan E23	GS59-631A
	GS21-463	87 – 93	Urvan E24	GS59-635
			Vanette C20, C120 All Models	GS57-086
		12/86 – 93	Vanette C22 Leaf Rear	GS59-635

SSANGYONG

	GS21-463	96 on	Musso	GS21-637S
--	----------	-------	-------	-----------

SUZUKI

	GS57-085	74 – 77	540, LJ10, LJ20, LJ50, LJ50V	GS57-086
	GS57-085	11/77 – 81	LJ81	GS57-086
	GS57-085	11/77 – 81	LJ80, LJ80V	
SD57-030	GS57-085	81 on	SJ40, SJ50	GS57-086
	GS57-613	98 on	Grand Vitara	GS57-639T
	GS57-615	98 on	Jimny SN413	GS57-616
	GS57-617	98 on	Jimny SN413 (Long Travel)	GS57-618
	GS57-085	81 on	Sierra, SJ/LJ 410/413	GS57-086

SD57-030	GS57-085	01/88 on	Sierra, Samurai SJ413, SJ414, SJ70	GS57-086
	GS57-613	88 on	Vitara	GS57-639T
	GS57-613	01 on	Vitara XL7 X92V	GS57-639T
		04/96 – 98	X-90 4WD	GS57-639T

TATA				
SD57-030	GS21-463	07/00 on	Safari 4WD All Models	

TOYOTA				
SD15-031	GS59-635	02/82 – 83	Blizzard LD10	GS59-635
SD59-021	GS59-639	To 08/85	4 Runner LN/RN/YN 60	GS59-650
SD59-033	GS59-088	08/85 – 89	4 Runner LN61, YN63 IFS	GS59-650
SD59-033	GS59-088	11/89 – 97	4 Runner LN/RN/YN VZN130, IFS	GS59-637
	GS59-222	1995 on	4 Runner / Surf RZN, KZN, VZN 185	GS59-223
SD59-021	GS59-639	79 – 07/83	Hilux LN/RN 36, 46	GS59-636
SD59-021	GS59-639	07/83 – 88	Hilux LN/RN/YN 65, 67	GS59-650
SD59-021	GS59-639	88 – 10/97	Hilux LN/RN/YN 105, 106	GS59-650
SD59-033	GS59-088	97 on	Hilux 165, 166, 167, 169, 170, 172, 174	GS59-650
SD59-033	GS59-088	88 – 97	Hilux LN/RN/YN 110, 111 SR5	GS59-650
SD59-033	GS59-088	09/91 on	Hilux LN 107/108, RN106	GS59-650
	GS43-082	68 – 04/72	Hilux RN10, 13, 15, 16 (2WD)	GS59-635
	GS43-082	06/71 – 83	Hilux RN20, 22, 25, 27, 30, 31, 40, 41 (2WD)	GS59-635
	GS43-082	07/78 – 83	Hilux LN30, LN40 (2WD)	GS59-635
	GS43-082	11/83 – 08/88	Hilux LN/YN 55, 56, 57, 58 (2WD)	GS59-636
	GS43-082	10/88 – 97	Hilux RN/LN/YN 80, 85, 86, 90 Grinner (2WD)	GS59-636
	GS43-082	10/97 on	Hilux RZN/LN 147, 149, 154 (2WD)	GS59-636
	GS59-222	00 on	Surf (Coil Spring)	GS59-223
	GS43-087	01/83 – 12/83	Hiace LH/YH 11, 50, 60, 61, 70, 71	GS59-635
	GS43-087	01/84 – 09/89	Hiace LH/YH 11, 50, 51, 53, 60, 61, 63, 71, 73	
	GS43-082S	10/89 on	Hiace LH/RZH 103, 113, 125	
SD59-023	GS59-635	59 – 75	LandCruiser BJ40, FJ40, HJ40	GS59-635
SD59-023	GS59-635	75 – 80	LandCruiser BJ40, FJ40, HJ40	GS59-636
SD59-023	GS59-635	80 – 84	LandCruiser BJ42, FJ40	GS59-636
SD59-023	GS59-635	To 07/80	LandCruiser FJ45, HJ45	GS59-636
SD59-023	GS59-635	07/80 – 85	LandCruiser FJ45, HJ47	GS59-636
SD59-023	GS15-639S	70 – 80	LandCruiser FJ55	GS59-636
SD59-024	GS59-637	Pre 10/85	LandCruiser FJ / HJ60, 61, 62	GS59-636
SD59-024	GS59-637	10/85 on	LandCruiser FJ / HJ60, 61, 62	GS59-650
SD59-024	GS59-637	85 – 12/89	LandCruiser FJ / BJ 70, 71, 73, 74 Leaf Spring	GS59-650
SD59-024	GS59-637	11/84 – 01/90	LandCruiser FJ75, HJ75	GS59-081
		11/84 – 01/90	LandCruiser FJ75, HJ75 (Big Bore)	GS59-079
SD59-024	GS59-637	90 – 09/99	LandCruiser FZJ75, HZJ75	GS59-081
		90 – 09/99	LandCruiser FZJ75, HZJ75 (Big Bore)	GS59-079
		09/99 on	LandCruiser FZJ78, HZJ78 (Big Bore)	GS59-079
		09/99 on	LandCruiser FZJ79, HZJ79 (Big Bore)	GS59-079
SD59-024	GS45-114	09/99 on	LandCruiser FZJ78, HZJ78 (Troop Carrier)	GS59-081
SD59-024	GS45-114	09/99 on	LandCruiser FZJ79, HZJ79 (Pickup)	GS59-081
SD59-024	GS45-114	09/99 on	L/Cruiser FZJ78/79, HZJ78/79 (Softer Opt. Big bore Rear)	GS45-115
SD59-024	GS59-637	90 on	LandCruiser Leaf Spring HZJ / PJZ 70, 73	GS59-650
SD59-024	GS59-632	94 on	LandCruiser Coil Spring KZJ 70, 73	GS59-631
SD59-024	GS59-634	94 on	LandCruiser Coil Spring Long Travel KZJ 70, 73	GS59-633
SD59-024	GS59-632	90 – 05/93	LandCruiser Coil Spring LJ / RJ 70, 73, 77	GS59-631
SD59-024	GS59-634	90 – 05/93	L/Cruiser Coil Spring Long Travel LJ/RJ 70, 73, 77	GS59-633
SD59-024	GS59-683	05/90 on	LandCruiser 80 & 100 Series	GS59-682
	GS59-782	98 on	LandCruiser 100 Series IFS	GS59-682
	GS59-222	96 – 03	LandCruiser Prado 90 Series	GS59-223

		03 on	LandCruiser Prado 90 Series (Big Bore)	GS59-225
SD59-024	GS59-632	87 – 96	LandCruiser II, Prado I LJ78/LJ79	GS59-631
SD59-024	GS59-634	87 – 96	LandCruiser II, Prado I LJ78/LJ79 Long Travel	GS59-633
	GS59-221	03 on	Prado 120 Series	GS59-637
SD59-024	GS45-114	11/84 – 12/89	LandCruiser Bundera LJ/RJ 70, 73	GS59-650 RH GS45-639B LH
	GS59-926	93 – 98	Rav4 SXA10, SXA11 (Front Strut Insert)	GS59-940
	GS59-927	05/00 on	Rav4 ACA20, 21, 22, 23	GS59-940
SD59-033	GS59-222	95 – 04	Tacoma V6	GS59-650